

ROAD MASTER'S REPORT

For the month of February 2021 Roadwork:

1. Plowed and cindered as needed during and after each storm
2. Widened intersections, Hollenback, Schmiegl, Allen, Spencer, Country View, Claverack, also bridges Fall Run & Glen
3. Widened Glen Road from Claverack to just above Falls
4. Had water coming onto our road at Harmony Hill turn around on top. Dug Ditch by hand to get water to stay off of the road.

Tucks and Equipment:

1. Repaired Trk 2 Headlight due to corrosion needed new relay
2. Tightened chain on spreader of trk 2
3. Flipped rubber edge on trk 2 and lowered rubber on trk 1
4. Replaced cutting edge on trk 3
5. Replaced heated wipers on trk 2
6. Replaced air filter on trk 1
7. Put new steel & rubber edge on trk 2 and rubber only on trk 1 plows
8. Tri-axle of salt delivered and stock piled
9. Greased trucks and spreaders
10. Replaced LH taillight bulb on trk 2
11. Greased backhoe
12. Filled trk 2 with Hydraulic Fluid
13. Greased Trk 2 dump box
14. Washed trucks and equipment after storms
15. Changed fuel filter on truck 4
16. Called PenDot on deer hit by car on Rt 6 near C&N Bank
17. Called PenDot on hole in road on Mercur near Fall Run intersection