ROAD MASTER'S REPORT

For the month of January 2025 Roadwork:

Road Work

- 1. Plowed and cindered multiple times as needed
- 2. Checked roads after heavy winds mainly limbs
- 3. Marked cross pipes for 811 on Glenn, Hollenback, Fall Run
- 4. Sign ran over at the plaza median replaced post and straightened signs
- 5. Picked up sticks at boat launch on walking trail
- 6. Plow got edge of berm at 90 Schmieg Road, racked and put back
- 7. Called Lecce Electric on Plaza traffic light due to getting calls from com-center. However, it is always working correctly when we get on site.
- 8. Did dash cam videos of road conditions on Red Rock, Fall Run an Harmony due to heavy truck traffic in the area
- 9. Had multiple cross-pipes that were frozen solid on the ends Dry Run, Harmony, Fall Run, Red Rock, Claverack. Used salt & metal bar to get open. Now flowing
- 10. Cut fallen tree to get through on West Valley (Standing Stone)

Tucks and Equipment:

- 1. Truck 1 spreader quit working. Found a bad Solenoid under the hood. Replaced and now works
- 2. Replaced rubber cutting edge on Truck 1
- 3. Truck 4 inspected, needed nothing
- 4. Replaced wipers on truck 1
- 5. Changed hose fittings on truck 1 plow. Was leaking
- 6. Greased spreader chains and spreader after each storm
- 7. Replaced rubber edge on v-plow truck 2
- 8. Washed trucks and checked fluids after each storm
- 9. Had right rear outside tire on truck 1 going soft. Took tire off, found screw, took tire to STTC for repair
- 10. Torqued all wheels on trucks

- 11. Found broken bolt on truck 2 v-plow that holds rubber stop plate. Had to drill out and use tap & die to make new threads. Installed new rubber stop & plate
- 12. Washed backhoe and greased everything on it. Checked fluids.
- 13. Charged battery on truck 3 spreader
- 14. Made a shield on truck 4 spreader due to spinner hitting taillight with anti skid and breaking light lens

Office

- 1. Swept and mopped shop office and bathroom cleaned sink and toilet
- 2. Attended winter maintenance class at the com-center
- 3. Put foam around shop main doors
- 4. Cleaned out drain box in wash bay 1