ROAD MASTER'S REPORT

For the month of February 2025 Roadwork:

Road Work

- 1. Plowed and cindered multiple times for snow and ice storms
- 2. Made dash cam videos of our roads, Dry Run, Red Rock, Fall Run, Hollenback, Claverack, due to heavy truck traffic.
- 3. Reset mailbox on Lundy due to being hit
- 4. Reported dead deer on 187 to PA Dot
- 5. Met Lecce Electric @ plaza traffic signal. He hooked his computer to our box to read cameras all working as they should. He did adjust the stop box bigger coming out of the plaza
- 6. Found multiple cross pipes plugged with ice used metal bar and got most exits open for water flow
- 7. Big tree fell on a table at Wysox Park, cut and removed tree and noticed table top was broken. Took pictures and sent to office
- 8. Cut multiple trees & limbs off roads and right of ways. Cleared ditches
- 9. Multiple locations of water ponding in roadways. Dug along berms for water to get off
- 10. Moved rocks off Glen Road at Falls multiple times

Tucks and Equipment:

- 1. Washed trucks 1 and 2 after each storm and spreaders
- 2. Found 2 bad wire ends on relay for plow on truck 2 put new eyelets on wires
- 3. Replaced air filter on truck 1
- 4. Greased both spreader chains after each washing and greased spreaders
- 5. Sharpened chain saws
- 6. Washed windows of trucks
- 7. Torqued wheels on trucks 1 and 2
- 8. Replaced rear foot pads on backhoe
- 9. Replaced right tail light and lens on truck 1, fixed mud flap
- 10. Greased backhoe

- 11. Greased under truck 2, ball joints, drive shaft
- 12.Installed fog lights on top of dumpbox on truck 2
- 13. Checked fluids in trucks before and after each storm
- 14. Purchased 2 sets of studded tire chains
- 15. Replaced heated wipers on truck 2
- 16. Noticed hair line crack on truck 2 wing plow, cleaned crack out and welded, sanded and painted
- 17. Cleaned battery terminals on trucks 1 and 2
- 18. Hose for grease on front drive sprocket came apart. Had to reset ferrel on hose and tighten down
- 19. Replaced power steering reservoir on truck 2. Original was leaking around top
- 20. Greased hinge pins on truck 2 dump box
- 21. Washed backhoe and windows

Office

- **1.** Cameras 9 through 12 at Wysox Park were offline. Found outlet, tripped reset breaker, cameras are now working
- 2. Stock piled 2 separate orders of Anti-skid. 1st order 210.90 tons, 2nd order 201.99 ton. Total, 412.89 tons
- 3. Ordered 2 separate orders of salt 21.54 ton and 19.88 ton for a total of 41.42 tons
- 4. Attended public works class through LTAP at BCCD
- 5. Installed AED Defibrillator cabinet above sink in meeting room